

AOI 25 - Hazardous Materials Storage Area Pad area located in the north end of Former Warehouse No. 3 looking south. This area is impacted with metals, PCBs in soil and VOCs in soil gas.



AOI 25 – View East of Hazardous Materials Pad Trenches and old slab beneath Warehouse No.3.








AOI 27 – View North of Former Hazardous Waste Storage Area impacted with PCBs impacted soil and concrete in the southwest corner of Former Warehouse No. 3.



View North of Former Oil Pump House (AOI 41) and Red Lead Shed (AOI 40) and Concrete stockpile located on former loading dock off northwest corner of the Main Building.








AOI 43 – View east of Cooling Tower & Basin for Plastic Molding Former Process Pit showing GS0025 and associated set-out samples. This area is impacted with metals, PCBs, SVOCs, and PAHs.



AOI 41 - View North of Former Oil Pump House area impacted with lead, arsenic and PCBs.








AOI 10: View West of Forklift Repair Area PCB impacted concrete and showing strips of replaced concrete.



AOI 10. Former Forklift repair area showing contrast between the older and darker PCB impacted concrete and the lighter more recent replaced concrete. Core samples are denoted by flags.








AOI 6: View West of Former Oxide Room Area within Main Building showing stained concrete and oxide grinder footings.



AOI 13: View North of Cast on Strap (COS) area on right and PCB impacted concrete (on left) in the Southeast part of the Main Building.







AOI 13 Area PCB impacted concrete in the southeast part of the Main Building showing a a more recent 1-inch layer of concrete on top of purple stained PCB impacted concrete beneath.



AOI 13: PCB impacted concrete core sample from south end of Main Building showing penetration of PCB containing material.



